

TECHNICAL INFORMATION

Lambretta

Date:	01.06.2018	Version	1
-------	------------	---------	---

Dear Lambretta Partner!

Important notice!

Occasionally it could occur, that on the V-series, the direction of rotation of the Pirelli tire on the front rim (Type: Pirelli Angel Scooter) is reversed. Use the indicator on the sidewall of the tire to check whether the direction of rotation is right. (refer to pictures below)
This does not represent a safety problem, but should be corrected before delivery to the customer or at the next customer service.

Caro parceiro Lambretta!

Aviso importante!

Pode ocasionalmente ocorrer, que o sentido de rotação do pneu Pirelli na jante dianteira (Tipo: Pirelli Angel Scooter) esteja. Use o indicador na parede lateral do pneu para verificar se o sentido de rotação está correto. (consulte as imagens abaixo)
Isto não representa um problema de segurança, mas deve ser corrigido antes da entrega ao cliente ou no próximo serviço ao cliente.

Direcção errada / Wrong direction



Direcção correcta / Right direction:



Report No.:	TIN_2018_LB_1_6	Done by:	Schorm
Model:	V50, V125, V200	Approved by:	Groll
VIN No.:	VDL ***** JS*****		
Page 1 / 1	SAFETY INFORMATION FRONT TIRE		